

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

GR965  
ENE  
> 1  
1.279 mi.  
6754 ft.

MANHOLE 62793  
SHORE PKWY - E 13TH ST  
BROOKLYN, NY

NY Spills S106698867  
N/A

Site 2 of 3 in cluster GR

Relative:  
Higher

Actual:  
13 ft.

SPILLS:

Name: MANHOLE 62793  
Address: SHORE PKWY - E 13TH ST  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0406055 / 2004-11-09  
Facility ID: 0406055  
Facility Type: ER  
DER Facility ID: 211008  
Site ID: 257705  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2004-09-01  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2004-09-01  
CID: 64  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2004-09-01  
Spill Record Last Update: 2004-11-09  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: ERT DESK

DEC Memo: "155163 Charles Lugo found 2 qts unknown oil on 1000 gallons water in MH62793. No sewers or waterways affected. Sample taken, Env. stop tag # 44585 placed. Clean up pending test results. Lab Sequence Number: 04-06969-001: Aroclor 1260 < 1.0 ppm Update - 9/3/04 - 1500hrs Structure dfaulted by #9 on 9/1/04 - tag # 02481 - tubing to joint off and below water line. 9/5/04 1750HRS S.ADEAPO ENVIR OPPS REPORTS FOUND EARTHEN SUMP IN STRUCTURE WILL CEMENT AND SEAL.CLEANUP CONTINUES. 9/5/04 1945HRS S.ADEAPO REPORTS DOULBED WASHED STRUCTURE USING BIO-GEN 760.SEALED SUMP.FOD MARKED PHASES .TAG REMAINS PENDING REPAIRS TO D-FAULT. 9/7/04 0110 HRS O.S MARTINO #12509 U/G REPORTS ALL WORK IS COMPLETED IN MH-62793. REMOVED ENVIR TAG#44585."

Remarks: "2 quarts of unknown oil on 1000 gallons of water in a manhole. No to 5 questions. Con-Ed #155163"

All Materials:

Site ID: 257705  
Operable Unit ID: 889607  
Operable Unit: 01  
Material ID: 487013  
Material Code: 0066A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported

Site ID: 257705  
Operable Unit ID: 889607  
Operable Unit: 01  
Material ID: 487014  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: L  
Recovered: .00  
Oxygenate: Not reported